

In the specification:

Please replace the paragraph beginning at page 13, line 33 and ending at page 14, line 2, with the following paragraph:

When the cam 28 is in the contact position, the shoe contacts the internal disk 36a. The shoe contact with the internal disk occurs due to pushing forces of the cam against the external disk 34 which pushes the internal disk against the shoe. Pressure on the external disk 34 from the cam 28, in the contact position, results in a pinching effect on the external disk 34 which causes a pinching effect on the internal disk 36.